

ANALOG CLAMP METER 7110

APPLICATION: This is an Analog Clamp Meter. This instrument can be used to measure, AC/DC Voltage, AC Current, Resistance, Temperature. It is an ideal tool for the Electricians, Engineers, Factories, Industries, Laboratories, Students, Household.

FEATURES:

- Display: Analog
- **CAT II 600V**
- Operating & Storage Temperature & Humidity: -5°C To 40°C, <75%RH
- Clamp Jaw Opening Size: 40mm
- Power supply: 1.5 Volt Batteries (AA size)
- Dimension: 198×80×36mm
- Weight: 320 gms Including Battery



SPECIFICATION:

DC Voltage

Range	Best Accuracy
60V	±(3% full range)

AC Voltage

Range	Best Accuracy
150V	±(3% full range)
300V	
600V	

AC Current

Range	Best Accuracy
6A	±(3% full range)
15A	
60A	
150A	
300A	

Resistance

Range	Best Accuracy
Rx1	±(4% of arc)
Rx100	Arc Length 35mm

DC Voltage

Range	Best Accuracy
Rx100	±5°C(0°C ~ 100°) ±10°C (Beyond the range)

ACCESSORIES:

Instruction Manual, Batteries, Test lead, Carrying Pouch.